

PORTABLE NUCLEAR GAUGE

Type A Package Labelling Requirements

REQUIRED LABELS

- ✓ Yellow-II hazard labels with radioisotopes, radioactivity and transport index indicated on two opposite sides of the package.
- ✓ UN Number and proper shipping name. This label must appear beside the Yellow-II, hazard label on both sides of the package.
- ✓ The package type, “Type A”.
- ✓ The VRI code, “USA”.
- ✓ Consignor and consignee address.



Yellow-II hazard labels, UN Number and proper shipping name on both the hinge side and clasp side of the case.

LABEL CONTENT

UN Number: UN3332
Shipping name: Radioactive Material, Type A Package, Special Form

Yellow-II hazard label
Radioisotope: Cs-137 / Am-241/Be or Am-241*
Radioactivity: 370 MBq 1480**
Transport Index: 0.5**

* Must match wording on shipping document
** This information will differ between gauge manufacturers and models.

Consigner and Consignee Address***

VRI code: “USA”
Package type: “TYPE A”

***It’s OK to be the same if it’s leaving from and coming back to your facility on the same trip.



Central Canada
Toll Free: +1 (800)-661-4591 | +1 (905) 602-8871
5949 Ambler Drive, Mississauga ON, L4W 2K2
www.stuarthunt.com

Western Canada
Toll Free: +1 (800)-661-4591 | +1 (780) 458-0291
15803 - 145 Avenue NW, Edmonton AB, T6V 0H8
www.stuarthunt.com