

# PORTABLE NUCLEAR GAUGE

## Type A Package Labelling Requirements

### REQUIRED LABELS

- ✓ Yellow-II hazard labels with radioisotopes, radioactivity and transport index indicated on two opposite sides of the package.
- ✓ UN Number and proper shipping name. This label must appear beside the Yellow-II, hazard label on both sides of the package.
- ✓ The package type, "Type A".
- ✓ The VRI code, "USA".
- ✓ Consignor and consignee address.



Yellow-II hazard labels, UN Number and proper shipping name on both the hinge side and clasp side of the case.

### LABEL CONTENT

UN Number: UN3332

Shipping name: Radioactive Material, Type A Package, Special Form

#### Yellow-II hazard label

Radioisotope: Cs-137 / Am-241/Be or Am-241\*

Radioactivity: 370 MBq 1480\*\*

Transport Index: 0.5\*\*

\* Must match wording on shipping document

\*\* This information will differ between gauge manufacturers and models.

### Consigner and Consignee Address\*\*\*

VRI code: "USA"

Package type: "TYPE A"

\*\*\*It's OK to be the same if it's leaving from and coming back to your facility on the same trip.

**Consignor:**  
Stuart Hunt & Associates Ltd.  
5949 Ambler Drive  
Mississauga, ON  
L4W 2K2

**Consignee:**  
Stuart Hunt & Associates Ltd.  
15803 - 145 Avenue N.W.  
Edmonton, AB  
T6V 0H8



#### Central Canada

Toll Free: +1 (800)-661-4591 | +1 (905) 602-8871  
5949 Ambler Drive, Mississauga ON, L4W 2K2  
www.stuarthunt.com

#### Western Canada

Toll Free: +1 (800)-661-4591 | +1 (780) 458-0291  
15803 - 145 Avenue NW, Edmonton AB, T6V 0H8  
www.stuarthunt.com