

PORTABLE NUCLEAR GAUGE

Type A Package Labelling Requirements

REQUIRED LABELS

- ✓ Yellow-II hazard labels with radioisotopes, radioactivity and transport index indicated on two opposite sides of the package.
- ✓ UN Number and proper shipping name. This label must appear beside the Yellow-II, hazard label on both sides of the package.
- ✓ The package type, "Type A".
- ✓ The VRI code, "USA".
- ✓ Consignor and consignee address.



Yellow-II hazard labels, UN Number and proper shipping name on both the hinge side and clasp side of the case.

LABEL CONTENT

UN Number: UN3332

Shipping name: Radioactive Material, Type A Package, Special Form

Yellow-II hazard label

Radioisotope: Cs-137 / Am-241/Be or Am-241*

Radioactivity: 370 MBq 1480**

Transport Index: 0.5**

* Must match wording on shipping document

** This information will differ between gauge manufacturers and models.

Consigner and Consignee Address***

VRI code: "USA"

Package type: "TYPE A"

***It's OK to be the same if it's leaving from and coming back to your facility on the same trip.

Consignor:
Stuart Hunt & Associates Ltd.
5949 Ambler Drive
Mississauga, ON
L4W 2K2

Consignee:
Stuart Hunt & Associates Ltd.
15803 - 145 Avenue N.W.
Edmonton, AB
T6V 0H8